

~~SECRET~~

PRIORITY

3 JUN 1964

OUT535376

P 022242Z
 FM NPIC WASHDC
 TO RUCSBR/SAC OFFUTT AFB OMAHA NEB
 RUCVAB/4080 STRAT WG OL 19 BARKSDALE AFB LA
 RUCVAB/2D RTS BARKSDALE AFB LA
 RUEAHQ/DIA WASHDC
 RUECYG/NAVRECONTECHSUPPCEN SUITLAND MD
 RUWBKN/15TH AF MARCH AFB RIVERSIDE CALIF
 RUWGAA/2AF BARKSDALE AFB LA
 BT
 S E C R E T CITE NPIC 2375.

~~HPB~~ _____~~CBS~~ _____~~CFC~~ _____~~PUS~~ _____~~ACI~~ _____

15TH AF (FOR DI), SAC (FOR DIM/GOLDEN TREE/DOCR, DM 4) 2D AF (FOR DI) (F e)

1. CAMERA B 101 WAS USED IN MISSION 3906 FLOWN ON 31 MAY 64;
 PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.

B. 9R SIDE: PRESSURE ROLLER STATIC (CHATTER) IS PRESENT AT THE BEGINNING OF THE MISSION ON BOTH SIDES OF THE FILM. MINOR EDGE STATIC IS FOUND INTERMITTENTLY ALONG THE INBOARD EDGE OF THE FILM. MINOR PROCESSING STREAKS ARE PRESENT THROUGHOUT. THE OUTBOARD FIDUCIAL MARKS APPEAR RAGGED DUE TO ACCUMULATIONS OF DUST ON THE FORMAT. NUMEROUS SMALL DIGS ARE LOCATED ON FRAMES 1, 898, AND 899. FINE PLUS DENSITY SCRATCHES, PARALLEL TO THE EDGE, ARE FOUND ON FRAME 348. WANDERING PLUS DENSITY STREAKS ARE PRESENT INTERMITTENTLY THROUGHOUT. A MANUFACTURER'S SPLICE IS LOCATED IN FRAME 294 AND IS FOLLOWED BY ASSOCIATED STATIC ON FRAMES 295 AND 297.

C. 9L SIDE: MINOR EDGE STATIC DISCHARGES ARE PRESENT ON BOTH EDGES IN FRAMES 000 - 600. FRAMES 000 - 300 CONTAIN INTERMITTENT

Declassification Review by NGA/DoD

~~SECRET~~

GROUP 1
 Excluded from auto
 downgrading and
 declassification

-PAGE 2-

DESENSITIZED SPOTS AND MINOR EMULSION DEFECTS. SMALL STATIC DISCHARGES ARE ALIGNED PARALLEL TO AND 1.25" FROM THE INBOARD EDGE IN FRAMES 001 - 023. A HEAT SPLICE IS POSITIONED BETWEEN FRAMES 1811/1812.

D. BOTH SIDES: A SMALL CIRCULAR FLARE APPEARS INTERMITTENTLY WITHIN THE FORMATS. ITS POSITION IS UNSTABLE AND IT IS NOT READILY DETECTABLE EXCEPT IN LOW DENSITY AREAS. BOTH SIDES CONTAIN TITLED FRAMES NUMBERED 0000 - 2084.

E. THERE WERE NO MAJOR CAMERA MALFUNCTIONS OR PROCESSING FAULTS.

3. POSITIVE:

A. THE PI SUITABILITY IS GOOD.

B. PRINTING AND PROCESSING WAS GOOD.

C. CLOUDS DEGRADE OR OBSCURE 30 PERCENT OF THE MISSION.

S E C R E T

/END OF MESSAGE/

((ABOVE MESSAGE ALSO PASSED CIA WATCH (CGS))

1